

Saint Paul Public Schools
 E-STEM Middle
 600 Weir Drive, Woodbury

sample date: 5/6/2018
 sampled by: Marissa Shepherd, Tod Eckberg, Natalie Bandy

First Floor

Room #	Location	2018 Sample Results	15 seconds Flush Sample	Comments
1711	Loading Dock	<2		
1806	Girl's Locker Room 1	<2		
1806	Girl's Locker Room 2	<2		
1803	Hallway Drinking Foutain 1	<2		
1803	Hallway Drinking Foutain 2	<2		
1806	Hallway Drinking Foutain 1	<2		replaced with Hydration Station
1806	Hallway Drinking Foutain 2	<2		
1811	Boy's Locker Room 1	<2		
1811	Boy's Locker Room 2	<2		
1702	Bathroom 1	<2		
1702	Bathroom 2	<2		
1702	Bathroom 3	<2		
1704	Bathroom 1	<2		
1704	Bathroom 2	<2		
1704	Bathroom 3	<2		
1030	Janitor Closet	<2		
1026	Unisex Bathroom	<2		
1609	Large Room	<2		
1606	Teacher Lounge	<2		
1603	Classroom Divider Sink	<2		
1611	Classroom Divider Sink	<2		
1500	Large Room	<2		
1504	Classroom Divider Sink	<2		
1508	Lab 1	<2		
1508	Lab 2	<2		
1508	Lab 3	<2		
1508	Lab 4	<2		
1508	Lab 5	<2		
1028 by Elevator	Drinking Fountain 1	<2		
1028 by Elevator	Drinking Fountain 2	3		
1024	Staff	<2		
1038	Kitchen 1	<2		
1038	Kitchen 2	<2		
1038	kitchen 3	<2		
1038	Kitchen 4	<2		
1038	Kitchen 5	<2		
1038	Kitchen 6	<2		
1038	Kitchen 7	<2		
1046	Nurse's Exam Room			
1045	Nurse			
1047	Nurse Bathroom	<2		
1044	Conference	<2		
1051	Teacher Bathroom	<2		
1106	Drinking Fountain 1	<2		
1106	Drinking Fountain 2	<2		
1005	Large Room	DNR		
1103	Classroom Divider Sink	3		
1108	Lab 1	<2		
1108	Lab 2	<2		
1108	Lab 3	<2		
1009	Drinking Fountain 1	<2		
1009	Drinking Fountain 2	DNR		
1007	Bathroom	<2		
1007	Bathroom	<2		
1007	Bathroom	<2		
1213	Large Room	<2		

1209	Classroom Divider Sink	<2		
1203	Classroom Divider Sink	<2		
1206	Teacher Lounge	<2		
1010	Janitor Closet	<2		
1012	Classroom	<2		
1016	Drinking Fountain 1	<2		
1016	Drinking Fountain 2	<2		
1017	Bathroom 1	<2		
1017	Bathroom 2	<2		
1017	Bathroom 3	<2		
1300	Large Room	<2		
1311	Classroom Divider Sink	<2		
1303	Classroom Divider Sink	2		
1306	Teacher Lounge	DNR		
1405	Large Room	<2		
1408	Lab	<2		
1409	Clean Room	<2		
1070		1 <2		
1074		1 <2		

Second Floor

Room #	Location	Sample Results	15 seconds Flush Sample	Comments
	2028 Drinking Fountain 1	DNR		
	2028 Drinking Fountain 2	<2		
	2032 Girls Bathroom	<2		
	2030 Boys Bathrrom	<2		
2027A	Staff Bathroom	<2		
	2608 Lab 1	<2		
	2608 Lab 2	<2		
	2608 middle 1	<2		
	2608 middle 2	<2		
2608A	2608 Lab 6	DNR		
	Lab Storage	<2		
	2603 Classroom Divider	<2		
	2509 Classroom Divider	<2		
	2505 Classroom Divider	<2		
	2506 Teacher Lounge	<2		
	2040	<2		
	2045 Copy Room	DNR		
	2053 Library	<2		
	2702 Mechanical Room	<2		
	2106 Teacher Lounge	<2		
	2105 Classroom Divider	<2		
	2108 Classroom Divider	<2		
	2008 Staff Bathroom	<2		
	2208 Middle 1	<2		
	2208 Middle 2	DNR		
	2208 Middle 3	DNR		
	2208 Lab Storage	<2		
	2203 Classroom Divider	<2		
	2007 Bathroom 1	<2		
	2007 Bathroom 2	<2		
	2007 Bathroom 3	<2		
	2012 Classroom	<2		
	2015 Janitor Closet	<2		
	2017 Bathroom 1	<2		
	2017 Bathroom 2	<2		
	2017 Bathroom 3	<2		
	2303 Classroom Divider	<2		
	2020 Bathroom	<2		
	2308 Middle 1	<2		
	2308 Middle 2	<2		
	2308 Middle 3	<2		
	2308 Lab Storage	<2		

2308A	Lab Storage 1	<2
2308A	Lab Storage 2	<2
	2408 Classroom Divider	<2
	2406 Teacher Lounge	<2
	2403 Classroom Divider	<2

Johnson Senior High
Location: 1349 Arcade St. Saint Paul MN 55106

Sample Date: 5/20/2018
Sampled by: Marissa Shepherd, Tod Eckberg, Natalie Bandy

Location	Sample Results	15 seconds Flush Sample	Comments
Kitchen DF 1	31	4	Flush Sign placed by Sink
Kitchen Sink 2	5		
1306	<2		
1310	<2		
1311	<2		
Custodial Bathroom A	<2		
Kitchen Before Bunn	<2		
kitchen water supply to bunn	<2		
kitchen prep sink outside 1412	<2		
n dishwasher sprayer just beyond dw	<2		
kitch LH spray in dw	<2		
kitchen LHM dw	<2		
kitchen RHM dw	<2		
Kitchen Hand sink dw	<2		
kitchen bathroom hand sink	<2		
1105	<2		
1106	<2		
1107 Bath L	<2		
1107 Bath M	<2		
1107 Bath R	<2		
1107 H/C Stall 1	<2		
1107 DF R	<2		
1107 DF L	<2		
Gym Corner DF	<2		
Library Staff Area	<2		
1204	<2		
1204 DF L	<2		
1204 DF R	<2		
1209 Private Staff	<2		
1209 Bathroom R	<2		
1209 Bathroom M	<2		
1209 Bathrrom L	<2		
1211	<2		
1214	<2		
1220	<2		
1220 DF L	<2		
1220 DF R	<2		
1224 L	<2		
1224 R	<2		
1224 SS	<2		
1301	<2		
1304 DF L	<2		
1304 DF R	<2		
1311 2	<2		
1003 L1	3		
1003L2	<2		
1003 M2	<2		
1003 R1	<2		
1003 R2	<2		
1003 HL 1	<2		
1009 Bathroom L	<2		
1009 Bathroom R	<2		
1009 1	<2		

1010 DF L	<2		
1010 DF R	<2		
1010 Maintenance	<2		
Nurse 1019	<2		
Nurse 1020	<2		
Nurse 1021	<2		
1025	<2		
1026 Bathroom	6		
1026 Sink	4		
Cafeteria DF	3		
Cafeteria Bathroom L	15	5	Flush Sign placed by Sink
Cafeteria Bathroom R	22	5	Flush Sign placed by Sink
1601 Girls L	2		
1601 Girl R	<2		
Gym 1601 DF L	<2		
Gym 1601 DF R	<2		
1601 Boys L	3		
1601 Boys R	4		
1601 Maintenance	<2		
Caf Hydration Station 1	<2		
Caf Hydration Station 2	<2		
0204 DF	11		
0205 Maintenance	17	10	Flush Sign placed by Sink
0208 DF	<2		
0208 Restroom L	<2		
0208 Restroom R	<2		
0208 L1	6		
0208 L2	3		
0208 M	<2		
0208 R	<2		
0212 DF	<2		
0214 DF	<2		
0216 1	<2		
02016 2	<2		
0218 L	<2		
0218 M	8		
0218 R	9		
0217 L	<2		
0217 M	4		
0217 R1	3		
0217 R2	<2		
DF301	<2		
301 Sink	2		
302 Bathroom 1	<2		
0304 A Maintenance	<2		
0306A L	<2		
0306A M	<2		
0306A R	<2		
0306 DF L	<2		
0306A DF R	<2		
0306A DF R2	<2		
0206B	<2		
0400 DFL	<2		
0400 DFR	<2		
0400 Girls L	<2		
0401 Girls L	50	3	Flush Sign placed by Sink
0401 Girls R	13		
2118 1	<2		
2118 2	<2		
2118 3	<2		
2118 4	<2		
2118 5	<2		
2118 6	<2		
2118 7	<2		

2118 8	<2	
2118 9	4	
2115 L1	<2	
2115 A	7	
2115 M	4	
2111 DF L	<2	
2111 DF R	<2	
2111 Bath H/C	<2	
2111 Bath L	<2	
2111 Bath R	<2	
2111 Bath M	<2	
2111 L	<2	
2111 R	4	
2112	<2	
2109	<2	
2113 Center 1	5	
2113 Center 2	11	
2113 L1	<2	
2113 R2	2	
21101	<2	
2103 Bath H/C	<2	
2103 DF L	<2	
2103 DF R	<2	
2103 Bath L	<2	
2103 Bath R	<2	
2103 Bath M	<2	
2101 Bath H/C	<2	
2101 Bath L	<2	
2101 Bath M	<2	
2101 Bath R	<2	
2102 Bath H/C	<2	
2102 Bath L	<2	
2102 Bath M	<2	
2102 Bath R	<2	
2106	<2	
2107 A	<2	
2222 Bathroom L	<2	
2222 Bathroom M	<2	
2222 Bathroom R	<2	
2222 Bathroom H/C	<2	
2222 Men	<2	
2222 Women	<2	
2101 DF L	<2	
2101 DF R	<2	
2301 DF	<2	
2301 Staff men Sink	<2	
2506	3	
2508	19	8 Flush Sign placed by Sink
2503 Staff Women	<2	
2503/2417 Df	<2	
2425	<2	
2213 1	<2	
2213 4	<2	
2213 2	<2	
2213 3	<2	
2213 5	<2	
2213 6	4	Fixture replaced
2213 7	<2	
2120 1	2	
2120 2	3	
2120 3	<2	
2120 4	<2	
2120 5	<2	
2120 6	<2	

2120 7	<2		
2120 8	<2		
2120 9	<2		
2122 Bath H/C	<2		
2122 Bath L	<2		
2122 Bath M	<2		
2122 Bath R	<2		
2119	<2		
2120 A	33	2	Flush Sign placed by Sink
2117 1	<2		
2117 2	<2		
2117 3	<2		
2205	<2		
2205 Hall DF L	<2		
2205 Hall DF R	<2		
2211	<2		
2220	<2		
2224	<2		
2224 DF L	<2		
2224 DF R	<2		