

Saint Paul Public Schools
 Water Sample Results
 Highwood Hills
 Building Number: 496

Sample Date: 10/24/2021
 Sampled by: Tate Schrantz and Chad Whylen

Sample #	Location	Sample Results 2021	15 Seconds Flush Sample	Fixture Type	Comments
496-001	Room 2309 Restroom	<2		Sink	
496-002	Room 2309	<2		Sink	
496-003	Room 2303	<2		Sink	
496-004	Room 2312	<2		Sink	
496-005	Room 2314	<2		Sink	
496-006	Room 2316	<2		Sink	
496-007	Room 2313	<2		Sink	
496-008	Room 2315	<2		Sink	
496-009	Room 2317	<2		Sink	
496-010	New Addition Girl's RR - Left	<2		Sink	
496-011	New Addition Girl's RR - Middle	<2		Sink	
496-012	New Addition Girl's RR - Right	<2		Sink	
496-013	New Addition Restroom - ADA	<2		Sink	
496-014	New Addition Boy's RR - Left	2		Sink	
496-015	New Addition Boy's RR - Middle	<2		Sink	
496-016	New Addition Boy's RR - Right	<2		Sink	
496-017	New Addition Hall Cooler by Restroom - Left	<2		Cooler	
496-018	New Addition Hall Cooler by Restroom - Right	<2		Cooler	
496-019	Room 2406	<2		Sink	
496-020	Kitchen Handwashing North Wall	<2		Sink	
496-020.1	Kitchen Sink Left	<2		sink	
496-020.2	Kitchen Sink Right	<2		sink	
496-020.3	Dishwash Room Sprayer	<2		sprayer	
496-020.4	Kitchen custodial slop sink	<2		slop sink	
496-020.5	Kitchen Restroom	<2		sink	
496-021	Kitchen Bunn Machine	<2		Bunn	
496-022	Room 2230	<2		Sink	
496-023	Staff Lounge 2005	10		Sink	
496-024	Nurse's Office 2220	<2		Sink	
496-025	Nurse's Treatment Room 2225	34	51	Sink	Flush Sample 496-025.5
496-026	Nurse's Office Restroom	<2		Sink	
496-027	Room 2203 Sink	>100	40	Sink	Flush Sample 496-027.5
496-027.1	Room 2203 Bathroom	48	34	Sink	Flush Sample 496-027.15
496-028	Room 2201	40	>100	Sink	Flush Sample 496-028.5
496-029	Room 2201 Restroom	57	8	Sink	Flush Sample 496-029.5
496-030	Cafeteria	86	>100	Hydration Station	Flush Sample 496-030.5
496-031	Room 2003			Fountain	Does not work
496-032	Room 2003	81	<2	Sink	Flush Sample 496-032.5
496-033	Upper Level Restroom Left	<2		Sink	
496-034	Upper Level Restroom Right	<2		Sink	
496-035	Upper Level Men's	56	<2	Sink	Flush Sample 496-035.5
496-036	Upper Level Women's Left	<2		Sink	
496-037	Upper Level Women's Right	51	100	Sink	Flush Sample 496-037.5
496-038	Room 2424	62	>100	Sink	Flush Sample 496-038.5
496-039	Room 2426	<2		Sink	
496-040	Outside of 2506	>100	40	Sink	Flush Sample 496-040.5
496-041	Outside of 2506	>100	54	Fountain	Flush Sample 496-041.5
496-042	Room 2507	<2		Sink	
496-043	Room 2506	69	47	Fountain	Flush Sample 496-043.5
496-044	Room 2506	>100	<2	Sink	Flush Sample 496-044.5
496-045	Outside of 2503	63	11	Sink	Flush Sample 496-045.5
496-046	Outside of 2503	22	<2	Fountain	Flush Sample 496-046.5
496-047	Room 2502	>100	<2	Sink	Flush Sample 496-047.5
496-048	Room 2502			Fountain	Does not work
496-049	Room 2503	59	<2	Sink	Flush Sample 496-049.5
496-050	Room 2503			Fountain	Does not work
496-051	Upper Level SW Restrooms	6		Hydration Station	
496-052	Upper Level SW Restrooms	88	>100	Water Cooler	Flush Sample 496-052.5
496-053	Upper Level SW Restrooms Girls Left	34	<2	Sink	Flush Sample 496-053.5
496-054	Upper Level SW Restrooms Girls Right	32	<2	Sink	Flush Sample 496-054.5
496-055	Upper Level SW Restrooms Boys Left	<2		Sink	
496-056	Upper Level SW Restrooms Boys Right	<2		Sink	
496-057	Room 2613A	>100	43	Slop Sink	Flush Sample 496-057.5
496-058	Outside 2606			Fountain	Does not work
496-059	Outside 2606	>100	41	Sink	Flush Sample 496-059.5
496-060	Outside 2603	13		Sink	
496-061	Outside 2603	>100	45	Fountain	Flush Sample 496-061.5
496-062	Gymnasium west	22	<2	Fountain	s don't work. Flush Sample 496-062.5
496-063	Room 1112 Kitchen	<2		Sink	
496-064	Room 1111 Boys	<2		Sink	
496-065	Room 1109 Girls	<2		Sink	
496-066	Outside Room 1111/1109	<2		Fountain	
496-067	Room 1110	<2		Slop Sink	
496-068	Outside Room 1603	<2		Sink	
496-069	Outside Room 1603	<2		Fountain	
496-070	Outside Room 1606	3		Sink	
496-071	Outside Room 1606	11		Fountain	
496-072	Lower Level SW Restrooms Left	<2		Cooler	
496-073	Lower Level SW Restrooms Right	<2		Cooler	
496-074	Lower Level SW Restrooms Girls Left	<2		Sink	
496-075	Lower Level SW Restrooms Girls Right	<2		Sink	

496-076	Lower Level SW Restrooms Boys Left	<2		Sink	
496-077	Lower Level SW Restrooms Boys Right	3		Sink	
496-078	Room 1613A	>100	>100	Slop Sink	ush Sample 496-078.5
496-079	Room 1502	<2		Sink	
496-080	Outside Room 1502	<2		Sink	
496-081	Outside Room 1502	31	41	Fountain	ush Sample 496-081.5
496-082	Room 1502	>100	<2	Sink	ush Sample 496-082.5
496-083	Room 1502			Fountain	Does not work
496-084	Outside Room 1506	<2		Sink	
496-085	Outside Room 1506	>100	93	Fountain	ush Sample 496-085.5

Results >20 ppb lead from 2021 (10/25/21) compared to 2016 lead in water testing results

Sample #	Location	2016 results	2016 flush results	Sample Results 2021	15 Seconds Flush Sample	Retest Monday 10/25/21	Fixture Type
496-025	Nurse's Treatment Room 2225	<2		34	51	<2	Sink
496-027	Room 2203 Sink	7		>100	40	3	Sink
496-027.1	Room 2203 Bathroom	N/A		48	34	4	Sink
496-028	Room 2201	11		40	>100	5	Sink
496-030	Cafeteria	<2		86	>100	<2	Hydration Station
496-037	Upper Level Women's Right 2414	<2		51	100	9	Sink
496-038	Room 2424	<2		62	>100	<2	Sink
496-040	Outside of 2506	<2		>100	40	3	Sink
496-041	Outside of 2506	33	<2	>100	54	8	Fountain
496-043	Room 2506	<2		69	47	<2	Fountain
496-052	Upper Level SW Restrooms 2610 lobby	7		88	>100	<2	Water Cooler
496-057	Room 2613A	19		>100	43	13	Slop Sink
496-059	Outside 2606	19		>100	41	10	Sink
496-061	Outside 2603	<2		>100	45	30	Fountain
496-078	Room 1613A	>100	8	>100	>100	76	Slop Sink
496-081	Outside Room 1502	<2		31	41	<2	Fountain
496-085	Outside Room 1506	8		>100	93	19	Fountain